

Series TTE

Explosion-Proof RTD Temperature Transmitter

-The

User Selectable Ranges, Optional LCD Display

CE APPROVED



The Series TTE Explosion-Proof RTD Temperature Transmitter is the ideal product for hazardous temperature measurement applications. The TTE series has seven pre-programmed temperature ranges that are selectable via an internal dip switch. For those applications that need a custom range, the transmitter can be easily configured for any range between -30 to 250°F with a minimum span of 40°F. The span and zero can be quickly adjusted with a simple push button design. The compact housing allows for the transmitter to be mounted in virtually any application.

Model	Stem Length	LCD Display
TTE-104-W	4″	No
TTE-106-W	6″	No
TTE-109-W	9″	No
TTE-112-W	12″	No
TTE-115-W	15″	No
TTE-118-W	18″	No
TTE-104-W-LCD	4″	Yes
TTE-106-W-LCD	6″	Yes
TTE-109-W-LCD	9″	Yes
TTE-112-W-LCD	12″	Yes
TTE-115-W-LCD	15″	Yes
TTE-118-W-LCD	18″	Yes

ACCESSORY

A-287, Mounting bracket for pipe or surface mounting (Includes bracket and two 2" U-bolts)

4-9/32 [108.74] (108.74] (108.74] (10.23/64 [263.13] (113.51] (263.13] (1/2 NPT (113.51) (269.06] (1/2 NPT (1/2 NPT (1/2 NPT) (1/2 NPT) (1/2 NPT)

SPECIFICATIONS

Temperature Sensor: Pt1000, 0.00385 DIN. Output Temperature Ranges: User selectable - any range between -30 to 250°F with a minimum span of 40°F. Temperature Limits: Ambient: 0 to 158°F (-18 to 70°C); Process: -30 to 250°F (-34.4 to 121.1°C). Accuracy: Transmitter ±0.1% FS; Probe ±0.3% FS. Thermal Drift Effects: ±0.02%/°C max. Response Time: 250 ms. Wetted Materials: 316 SS. Process Connection: 1/2" male NPT. Conduit Connection: 1/2" female NPT. Probe Length: 2" to 18" (depending on model). Pressure Limits: 2000 psi (137.9 bar). Power Requirements: 10 to 35 VDC. Output Signal: 4 to 20 mA (two wire loop powered). Optional Display: 2 lines X 8 character LCD. Enclosure Rating: NEMA 4X (IP66) and explosion-proof for Class I, Groups B, C, D; Class II, Groups E, F, G; Class III. Weight: 2 lb 8 oz (1134 g). Agency Approvals: CE, FM.

 Field-Selectable Ranges

 40 to 90°F (4.4 to 32.2°C)

 -20 to 140°F (-28.9 to 60°C)

 0 to 100°F (-17.8 to 37.8°C)

 30 to 240°F (-1.1 to 115.6°C)

 32 to 212°F (0 to 100°C)

 32 to 122°F (0 to 50°C)

 -30 to 65°C (-1.1 to 18.3°C)

 Custom range between -30 to 250°F (-34.4 to 121.1°C)